




Poly Tab at End of back Support Should Point Downwards



Step 3

Attach the second side assembly by repeating Steps I & 2.

Step 4

ICounter, Bar & XT Heights Onlyl

